



BUSH FOR DIE LIFTING BOLT

2132.10.03. .1



Mounting example



Description:
Bush for casting-in, for lifting bolts 2132.10./11.

Material:
1.0308 (E235)

2132.10.03. .1 Bush for die lifting bolt

Order No	d ₁	d ₂	d ₃	l	Number of grooves
2132.10.03.032.1.1	32	44	34	40	1
2132.10.03.040.2.1	40	52	42	50	1
2132.10.03.050.3.1	50	62	52	60	1
2132.10.03.063.4.1	63	75	65	80	1
2132.10.03.076.5.1	76	100	78	100	2
2132.10.03.076.6.1	76	105	78	100	2