



GAS SPRING, SMALL DIMENSION AND LOW FORCE MOUNTING VARIATIONS


2480.051.00150



2480.053.00150



2480.054.00150



Note:

2) Attention:
The spring force must be
absorbed by the stop Surface!

Mounting examples:

